MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
Copy 7	Disposal & duly to the final place of deposition with all lead upto the Engineer in charge as directed by the Supervisor					93.38 Cft	7327/
	Certificate						
	(1) Work done is satisfactory						
	(2) There are no departmental Muccadam due						
	(3) Contractor has cleared all debris from the site						
	Nagaraj.R						

M. A. R. 57 (Rule 116)
Measurement Book

No. B 415324

Name of Work ...

Name of Contractor or nature of Agency ... From Bagalagunte To Doddamarannalayout) in Bagalagunte W-No16

Date of commencement of work ...

Reference to last Measurement 8	Full description, etc, of work	Dimensions				Contents 7	Reference to last Measurement 8
		Number 3	Length 4	Breadth 5	Depth 6		
	From Bagalagunte Layout is (From ... at municonda layout (Cuttings and Earthpaging to Doddamarannalayout) in Bagalagunte W-No16						
	 						

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬಿ.ಜಿ.ಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬೊಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ